



Figure 73. View of quoins, west wall, showing present condition and, right, minor cracks in roughcast.

Figure 74. Detail, quoins, west wall.

